

Mr. R. Seager Pump Cottage 6 Main Street Rotherby Melton Mowbray Leicestershire LE14 2LP.

BY EMAIL ONLY: robseager@hotmail.co.uk

Date: 24th October 2018.

For the attention of: Mr. R. Seager.

Dear Sir,

Re: Percolation Testing – All Saints Rotherby.

Following the receipt of your recent instructions we attended site on Saturday 20th October and completed Percolation testing to three no. holes following the specific instructions as set out within John Dodsons' email of 1st May 2018. (Copy attached).

Hole no. 1 – located at 5.5m away from the South West corner of the tower. Following complete drain away of the first water fill the hole was filled with water and drainage timing commenced at 12.00.30. The water had completely drained by 12.11.15 giving a drain time of 10 minutes 45 seconds.

<u>Hole no. 2 – located at 9.0m away from the South West corner of the tower.</u> Following complete drain away of the first water fill the hole was filled with water and drainage timing commenced at 12.06.15. The water had completely drained by 12.30.40 giving a drain time of 24 minutes 25 seconds.

<u>Hole no. 3 – located at 12.0m away from the South West corner of the tower.</u> Following complete drain away of the first water fill the hole was filled with water and drainage timing commenced at 12.07.15. The water had completely drained by 12.44.00 giving a drain time of 36 minutes 45 seconds.

We can confirm that no remains or items of interest were found during the dig and on completion of the testing all holes were back filled.











GRJ Contracting Ltd

Tel: 01664 434 999 Fax: 01664 434 999

www.grjcontracting.com

Email: contact@grjcontracting.com

GRJ House 14a Digby Drive Melton Mowbray Leicestershire

LE13 ORQ

Photographs were taken during our attendance as attached.

We trust that this provides the information required, if you would like to further discuss please do not hesitate to contact us.

Yours Faithfully,

Gary Bryan.



Hole 1.



Hole 2.



Hole 3.



Three holes.





Testing underway.



Testing underway.



Holes backfilled on completion.