

Certificate of Practical Completion

Issued By: Byrom Clark Roberts	Employer: The Vicar & PCC of St Mary	Project:	St Mary High Crompton Lobby Works
Washbrook House, Talbot Road Old Trafford, Manchester	High Crompton c/o St Marys Vicarage	Job No:	5117/0895/G11
M32 0FP	18 Rushcroft Road, High Crompton Oldham OL2 7PP	Certificate No:	PC 01
Contractor: Paul Smith & Co	Project: St Mary High Crompton:	Contract Date:	27 th September 2018
Lomax House, Lomax Street Rochdale	Lobby Works	Issue Date:	30 th January 2019
OL12 OJR			

This Certificate of Practical Completion is issued under the terms of the above mentioned contract. For the avoidance or removal of doubt the issue of this Certificate is not intended to show and shall not be taken as showing that any work or materials or goods or workmanship is or are accepted as conforming to description or as being in accordance with The Contract.

We certify that, subject to the completion of any outstanding items and making good of any defects, shrinkages or other faults which appear during the defects liability period, that:

the works were in our opinion practically complete, as defined in Clause 2.9 on:

Friday 18th January 2019

and that the said defects liability period will end on:

Thursday 19th July 2019

Note:

One moiety of the retention moneys deducted under previous certificates in respect of the works or part thereof is to be released in accordance with the contract conditions.

Signed Contract Administrator	la	For Byrom Clark Roberts Limited		
Distribution				
Employer	BCR. Architect	Project Manager	Service Engineers	
Contractor	BCR. Engineer	Structural Engineer	Sub Contractors	
Clerk of Works	BCR. Surveyor	Quantity Surveyor	CDM Co-ordinator	

St Mary High Crompton: Lobby Works

List of Defective Items to be rectified.

- 1. Where the old doorstop was located on door D1, this has been infilled with a mortar repair, but this patch needs to be polished and toned down to appear more discrete.
- 2. The new distribution board has also been installed in the outer lobby. However, a new earth cable needs to be painted out in the wall colour.
- 3. There are also some scuffs and marks on the South side of the existing screen, which need to be carefully touched up.
- 4. The holes for the old hinge fixings on the East side of door D2 to the screen need to be carefully infilled with dark wood filler. Ditto to the West side.
- 5. On the interior of the Church some additional touching up to the plaster and emulsion decoration are required. On the West gable wall, in the South-West corner, where some chasing has been done, some fine plaster patching and decoration is needed to 'make good'.
- 6. Ditto to the wall on the South side above the entrance where cables have been adjusted to the emergency exit light. Again, the plaster and finish decoration needs to be made good.

List of Additional Items instructed

- 7. The existing door-stay has been retained to the outer door D1. This door swings both ways and there is a need to install outer doorstops to prevent the door from damage.
- 8. A doorstop should also be installed to the inner screen door D2. Again to protect the door.
- 9. Existing conduit, to the North-East corner of the outer lobby, is redundant. This should be removed.

IWL

Signed Contract Administrator	1a	For Byrom Clark Roberts Limited		
Distribution Employer Contractor Clerk of Works	BCR. Architect BCR. Engineer BCR. Surveyor	Project Manager Structural Engineer Quantity Surveyor	Service Engineers Sub Contractors CDM Co-ordinator	