

Chancel roof



North Aisle Parapet



North Aisle



North Aisle



Organ chamber & North



Ground Gutter north of Tower



Ground Gutter west of porch



Ground Gutter east of porch




Ground Gutter south of aisle



Ground Gutter south of Lady Chapel





South aisle



South gate





South Aisle West Window



South Aisle West Window



South Aisle West Window











































**Photo-Sheet Index**

<b>Sheet 1</b>	<b>Primarily Masonry Repairs</b>	<b>Sheet 2</b>	<b>Primarily Window Repairs</b>
1	Church from south east	19	South aisle, west window
2	Church from south and north	20	Detail s aisle, w window & gulley
3	Church from north east	21	Porch parapet s & s central window
4	South aisle parapet & detail	22	South central window
5	South aisle parapet detail	23	South eastern window
6	Porch roof & porch se corner	24	South western window
7	Porch roof nw & ne corners	25	North western window
8	Aisle parapets, east end	26	East window
9	Lead and ne aisle parapet corner	27	Vestry window and light
10	North aisle parapet and detail	28	North central window
11	North face rainwater downpipes	29	North central window
12	Ground gutter north of tower	30	North central window
13	Ground gutter west of porch	31	Barrel and north western window
14	Ground gutter east of porch	32	North western window
15	Ground gutter south of aisle	33	West window
16	Ground gutter south east corner	34	West door external view
17	South aisle pillar	35	West door detail
18	South gate	36	Ringing chamber window - external
		37	Ringing chamber window - internal