

A close-up photograph of a gas valve and its associated piping. The valve is a small, cylindrical metal component with two pipe connections. The piping is made of dark, flexible material, possibly braided steel or reinforced plastic. The background wall is made of light-colored plaster, which is severely deteriorated, with large areas of peeling and cracking. A vertical crack runs down the wall, passing through the valve assembly. The overall condition suggests significant age and potential safety hazards.

A photograph of the interior of a tomb, showing a curved wall covered in yellow and red painted patterns, possibly representing a tiled surface. The floor is dark and uneven.



Drawn JW	Checked MC	Rev A	Notes For List B / Faculty and Tender	
Job 0281	Job STOCKLAND BRISTOL St Mary Magdalene's			
016-2	Title Proposed Tower Roof & Tower Floor Plans			
Scale 1:50 at A1		This document is copyright and the property of Chantry Conservation Architects Ltd. Any copies of this drawing made by any method must also include a copy of this legend.		