

January 2017: Clock chamber: fallen ceiling board (& dislodged dust/debris) and other boards also splitting 2016 - cleared out & boards re-secured 2017





March 2017: clock connecting rod damaged by ceiling board falling on it +broken tooth on pin wheel escapement 2016, repaired & reinstated 2017



June 2017 automatic winding installed: extra framework clamped (not bolted) to existing frame, new weights & pulleys, battery backup attached to cupboard

