



Approach to the car park from the north

View from the tower looking NW.



Boundary wall

Porch

Path since laid to temp
hoggin surface



View from outside west door looking north.



View of carpark looking north.



North porch entrance and temporary hoggin path.



West door looking in



West end of building