St Mary's Church, Denham – Chancel Roof (South side) – Repairs to the cracked lead rolls Faculty number 2022-074255









Robert Ash, St Mary's Fabric Team, 23 June 2023