

Handrail in St Leonard's Church Butleigh Tower

An assessment of the climb for bellringers up and down to the bellringing chamber showed that there was a potential for a slip or fall if there was no rail or other aid to grasp. So far no slips or falls had occurred, but the risk was there. Also, such a rail might aid some ringers as they became older. It seems prudent to provide a hand rail in the tower.