
-Weathercock on decayed

wooden post in centre of roof and 3no iron stays

Vice turret roof in very

poor condition









Vice Turret Roof with Weathercock base Photo Credit: Sally Strachey Historic Conservation Ltd

