


Reference	Condition	Action	Priority	Cost£	Photograph
2.	Dark oak Bishop's chair (1622); in reasonable condition.				
3.	Remaining panelled oak pews in centre and west end of Nave and at sidewalls in aisles (1878); in good condition.				
4.	Oak secondary altar and upholstered beech chairs in Lady Chapel in good condition.				
5.	Octagonal stone font (C15?) with oak cover; in reasonable condition.				
6.	Oak chest in Tower (1708) is heavily wormed: said to have been treated; fresh frass visible.	Re-treat with insecticide.	B(M)	60	
7.	Numerous other tables, chairs and chests of drawers in reasonable condition.				
8.	Tomb cover with effigy (C14) set into floor; fair condition.				

10.13 Organ

1.	Pipe organ by Thomas Hopkins & Son, York, rebuilt by Abbot & Smith of Leeds (1958). Bellow removed (2013), and electromagnetic function added (2024). Last tuned 06.05.25, said to function well.	Commission service.	A	?	
----	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------	---	---	--

10.14 Accessibility

1.	Fully accessible from highway at southeast except for the Chancel. No designated parking bay.				
----	-----------------------------------------------------------------------------------------------	--	--	--	--