

Re: Covenham St Mary 290620



From wayne francis <awf24k@hotmail.com>
To ballantyne@doctors.org.uk <ballantyne@doctors.org.uk>
Date 2020-06-30 19:46





Hi Jenny

They sound nice. The older two have been hand chisel turned at some point, probably when they added the latest bell to try and match them up.

Details attached.

Hopefully you will have a go on them. Very easy to chime. Hopefully get some village children involved. They absolutely love making bells clang! This way it is totally safe for them, they can do no harm to the bells etc.

Thanks
Wayne

Place	Covenham St Mary Annunciation BVM
Grid Ref	TF339943
Lat, Long	53.42866, 0.01469 (Locate using Google Map or OS Map or OpenStreetMap)
Postcode	LN11 0PG
SatNav	No optimised destination for Satellite Navigation has been submitted Add deta
County	Lincolnshire
Country	England
Diocese	Lincoln
Church	Church of England
Listed Gr	II* See Heritage website
TowerBase	7368
Bells	3 U/R (see below) Edit Details
Tenor	7cwt (~780lb or ~360kg) in C
Frames	1 Show Details
Additional information	Unringable

Covenham St Mary, Lincolnshire Annunciation BVM								
Bells Hide Details								
Bell	Weight	Nominal	Note	Diameter	Dated	Founder	Canons	Turning
1			E	27.00"	c1499†	William Chamberlain	R	
2			D	33.00"	1822	James III Harrison	R	
3	7cwt		C	33.00"	1726	Daniel Hedderly	R	
Source: GAD; Dove tenor wt; D Sloman; J Greenhough								
Contributed by: George Dawson Last updated: 04/08/2017								

From: ballantyne@doctors.org.uk <ballantyne@doctors.org.uk>
Sent: Tuesday, June 30, 2020 7:23:28 PM
To: wayne francis <AWF24K@hotmail.com>
Subject: Re: Covenham St Mary 290620

Dear Wayne

Thanks so much for that. What do the bells sound like?

I will transfer the money asap

Jenny