

ALL SAINTS, CHEVINGTON, SUFFOLK: PHOTOGRAPHS OF CHANCEL ROOF PROJECT

PHOTOGRAPHS BEFORE WORK



1. Chancel exterior from south



2. Chancel roof seen from nave



3. Chancel south roof slope detail looking east



4. Chancel south roof slope detail looking north west

PHOTOGRAPHS DURING WORK



5. Chancel roof looking south during stripping 27/10/2017



6. Chancel roof looking north east decking completed 30/11/2017



7. Stainless steel roof tray preparation underway 30/11/2017



8. Stainless steel roof tray laying underway 8/12/2017



9. Stainless steel roof tray laying underway 8/12/2017



10. Stainless steel roof capping laying underway 19/12/2017



11. Eaves detail underway 19/12/2017



12. Flashing work underway 19/12/2017



13. General roof and flashing work complete 21/12/2017



14. General roof and flashing work complete 21/12/2017

PHOTOGRAPHS OF COMPLETED WORK

Whitworth
18 Hatter Street
Bury St Edmunds
Suffolk
IP33 1NE

PEO/peo/C144/8
2nd January 2018