## 2. Architect/Surveyor (if any)

(i) The architect/surveyor employed in relation to the work was:

Name: Julia Vallin, Jave Jones - Warner Associates

Address: Unix 78 Chiverto Ontopio Cate, Termino Road Chicata

- (ii) The above named architect/surveyor
  - (a) was provided with a copy of the faculty before work commenced; and
  - 74 June 2019 (b) has issued a Practical Completion Certificate dated in relation to [the whole] [part] of the works. (Delete as appropriate)

## 3. Certificate by Churchwardens or Petitioner

- (i) We/I certify to the best of our knowledge, information and belief that the works have been carried out in accordance with the faculty.
- (ii) We/I certify that all the conditions attached to the faculty have been complied with.
- (iii) We have given a copy of the certificate to the Archdeacon and have placed a copy in the church's log book.

(Delete (iii) in the case of works to a building included in the list under the Care of Places of Worship Measure 1999)

(In each case below insert the name of Churchwarden (except in the case of works to a building included in the list under the Care of Places of Worship Measure 1999), Petitioner or person authorised to act on Petitioner's behalf)

Name:

Noma Unt, Chimeraen

Address: 20 okebrue Crescut, Leja Park, Kayoline

Date:

20/6/18

Name:

Par Willow, Chuncose

Address: 88 Blandmas Cremen Legis Parl Unnul

Date: 20/6/19

Signed: MAK Waran

Note: This form is to be returned to the registrar within 28 days of the practical completion of the work