Practical Completion



Issued by: Soul Architects Limited

Address: 13 Sparken Hill, Worksop, Nottinghamshire, S80 1AX

Employer: East Drayton PCC Job Reference: 9025

c/o Mrs Janet Goddard,

Address: janetgoddard10@gmail.com

Contractor: Wayne Francis Clockwise Restoration Certificate No: 01

Address: Fair View, Algarkirk. Boston. Lincs. PE202LJ Issue Date: 28-09-20

Works: West Tower Clock Restoration

Situated at: St Peters Church East Drayton

Agreement dated: -

Under the terms of the above-mentioned Agreement,

I/we hereby certify that in my/our opinion

Practical Completion of the Works has been achieved

*Delete or strikethrough if not applicable *and the Contractor has complied with the contractual requirements in respect of information for the Health and Safety file

on _____11th September _____ 20 20_____

Signed _____

For and on behalf of Soul Architects Limited

-		_	1			1	1
Distribution:	Employer		Contractor	Quantity Surveyor	Structural Engineer	CDM Consultant	File