Ref: 2020-056087 Church: Dewsall w Callow: St Michael

Diocese:HerefordArchdeaconry:HerefordCreated By:Mr David HowellContact Tel.:01432354858

Status: Faculty granted, awaiting Practical Completion

Form 8

(Rule 7.4)

Certificate of practical completion of works authorised by faculty

In the Consistory Court of the Diocese of Hereford

To the Registrar

Parish of Dewsall with Callow

Church of Dewsall w Callow: St Michael

A faculty dated 06/07/2021 authorised the following works subject to the following conditions:

Restoration of the bells (c1450-1500) and return of third bell to the church having been removed from the redundant Hereford, St Francis. All in accordance with Nicholson's Inspection report dated 12th November 2020; Pearce Edward's report dated 12th February 2021; Pearce Edward's sketch drawing SK1; Statement of Need and Statement of Significance.

- 1. No works to proceed unless and until Registrar reasonably satisfied as to funding.
- 2. Insurers recommendations in email 8.4.21 to be observed.
- 3. Recommendations of Diocesan Bells Adviser to be observed so far as reasonably possible.
- 4. Copy Form !A to be completed, signed, filed and uploaded.

Note this does not permit tuning of the bells.

R Kaye QC, Ch

1. Company, first or person by who work carried out

The work was carried out by the following:

Bells restoration and installation: Nicholson Engineering Ltd.

Each company, firm or person named above was supplied with a copy of the faculty before the work was commenced.

2. Architect/Surveyor (if any)

(i) The architect/surveyor employed in relation to the work was:

Name: N/A
Address: N/A

- (ii) The above-named architect/surveyor
 - (a) was provided with a copy of the faculty before work commenced; and
 - (b) has issued a Practical Completion Certificate dated in relation to part of the works.

3. Certificate by churchwardens or petitioner

- (i) I certify to the best of my knowledge, information and belief that the works have been completed in part and that details of the works that have not been carried out are set out in the letter to the registrar which accompanies this certificate and that the works carried out are in accordance with the faculty.
- (ii) I certify that all the conditions attached to the faculty have been complied with.
- (iii) I have given a copy of the certificate to the Archdeacon and have placed a copy in the church's log book.

Name: David Howell

(Churchwarden, St. Michael &

All Angels, Dewsall)

Address: Farmore, Dewsall Herefordshire HR2 8DB

David Howell

Signed:

Date: 4 March 2022

Note: This form is to be returned to the registrar within 28 days of the practical completion of the work.

Works not completed