





Repaired window south aisle.



Repaired tower west window





Gully 1 and replacement RWP section.



Gully 2 repair.



Gully 3 repair.





Gully 4 repair



Gully 5 repair



Gully 6 repair





Gully 7 repair



Gully 8 repair



Gully 9 repair



Broken concrete repair, there was no pipe below.