

# Practical Completion



**Issued by:** **Soul Architects Limited**  
**Address:** 13 Sparken Hill, Worksop, Nottinghamshire, S80 1AX  
**Employer:** **St John's Worksop PCC,**  
**Address:** St Johns Church, Overend Rd, Worksop S80 1QG  
**Contractor:** **Pinnacle Conservation Ltd**  
**Address:** The Raylor Centre, James Street, York, YO103DW

Document ID:

Job Reference: 9305

Certificate No: **PCL-PC01**

Issue Date: 16-06-24

**Works:** **St John's Church, Worksop – South Aisle Repairs**

**Situated at:** St Johns Church, Overend Road, Worksop

**Agreement dated:** -

Under the terms of the above-mentioned Agreement,


I/~~we~~ hereby certify that in my/~~our~~ opinion

Practical Completion of the South Aisle Roof Repairs at St Johns Church Worksop was achieved.

\*Delete or strikethrough if not applicable

~~\*and the Contractor has complied with the contractual requirements in respect of information for the Health and Safety file~~

on 14<sup>th</sup> June 2024

Signed   
 For and on behalf of Soul Architects limited

Distribution:	Employer	Contractor	Quantity Surveyor	Services Engineer		
	Structural Engineer	Clerk of Works	Planning Supervisor			File