

Ref: 2017-008155 Church: Thornton-in-Lonsdale: St Oswald
Diocese: Leeds Archdeaconry: Richmond and Craven
Created By: Mrs Rosemary Hartley Contact Tel.: 015242 42207
Status: Faculty granted, awaiting Practical Completion

Form 8

(Rule 7.4)

Certificate of practical completion of works authorised by faculty

In the Consistory Court of the Diocese of Leeds

To the Registrar

Parish of Thornton in Lonsdale

Church of Thornton-in-Lonsdale: St Oswald

A faculty dated 19/02/2018 authorised the following works subject to the following conditions:

Improvements to heating and electrical provision: Two BN Thermic radiant box type heaters in the chancel, fixed around the springing point of the chancel arch, to replace old radiant heaters that will be removed. Two additional BN Thermic radiant box type heaters in the south aisle, fixed below the colonnade. Two double power sockets in the sanctuary sited by the altar rail on the north and south walls at low level, and one double power socket at the east end of the north aisle at low level on the masonry column. All sockets to have metal back boxes and face plates generally to match existing similar examples in the church. All cabling to be in MICC. As described in a letter from Mike Darwell (inspecting architect) dated 12 October 2017, JCA plan dated November 2017 (ref 1672/01), JCA document "Proposals for suspended radiant heaters", Thomas Handley quote dated 23 March 2017, and "photographic evidence" document.

On condition that the advice of Historic England is followed.

1. Company, first or person by who work carried out

The work was carried out by the following:

(If a different company, firm or person was employed for different items of the work details of each must be given.)

THOMAS HANDLEY

Each company, firm or person named above was supplied with a copy of the faculty before the work was commenced.

2. Architect/Surveyor (if any)

(i) The architect/surveyor employed in relation to the work was:

MIKE DARWELL

Name: MIKE DARWELL.

Address: NO 3 UNSWORTH'S YARD

FORD ROAD

CARMEL, CUMBRIA, LA11 6PG

- (ii) The above named architect/surveyor
 - (a) was provided with a copy of the faculty before work commenced; and
 - (b) has issued a Practical Completion Certificate dated in relation to part of the works.

3. Certificate by churchwardens or petitioner

- (i) We/I certify to the best of our knowledge, information and belief that the works have been carried out in accordance with the faculty.
- (ii) We/I certify that all the conditions attached to the faculty have been complied with.
- (iii) We have given a copy of the certificate to the Archdeacon and have placed a copy in the church's log book.

Name: ROSEMARY HARTLEY
Address: LINTONDALE, RABBIT TOP LANE, INGLETON.
Signed: R. Hartley
Date: 5/9/24.

Note: This form is to be returned to the registrar within 28 days of the practical completion of the work.